




R41 - 470 ohms, BF = 250, C31 = 1 ufd  
 Risetime = 1.3 milliseconds, Fall time = 6.1 milliseconds



R41 - 470 ohms, BF = 170, C31 = 1 ufd  
 Risetime = 1.3 milliseconds, Fall time = 5.5 milliseconds



R41 - 470 ohms, BF = 50, C31 = 1 ufd  
 Risetime = 2.3 milliseconds, Fall time = 3.3 milliseconds



R41 - 150 ohms, BF = 170, C31 = 2.2ufd  
 Risetime = Fall time = 5 milliseconds